

X009-FD1 Mounting Height Adjustment

This will allow the headunit face to open in case it is hitting the bezel.

In some F-150 vehicles the X009 headunit may sit too high up against the top edge of the radio bezel preventing the face from opening. (See image 1). Use the instructions below to correct the problem. (See image 2)

