

## **X109-WRA & X110-SLV/SRA Sound Only From Right Side Of Vehicle**

1. The CAM/AUX/DATA harness is not pinned correctly.
2. The White wire needs to be positioned in between the black wire and the red wire.

