| Alpine Restyle Systems Accessory Module and Installation Accessory Matrix |   |                                 |                                    |   |                            |  |               |                     |                           |  |  |   |
|---|---|---------------------------------|------------------------------------|---|----------------------------|--|---------------|---------------------|---------------------------|--|--|---|
| ✓ Compatible X Not Compatible N/A Not Applicable                          |   |                                 |                                    |   |                            |  |               |                     |                           |  |  |   |
| Module/Accessory  |   | Satellite Tuner                 | Multi Camera<br>Selector Interface | External<br>Accessory<br>Control Module | HDMI Selector<br>Interface | Camera Input<br>Harness for OEM<br>Radio | Rear Camera   | GM Bose Interface   | Tailgate Handle<br>Camera | Optional 3rd Party Parts(not included) |  |   |
| Head Unit   | Vehicle   | SXV300                          | KCX-250MC                          | KCA-001                                 | KCX-630HD                  | ALPHRN-CAMCH                             | HCE-TCAM1-WRA | KCX-BOSE-GM         | HCETG130-GM               | Pac-Audio<br>GMRVD2                    | iDatalink SP1 Warning<br>Chime Speaker | MetraAUX-USB-35EXT /<br>Scosche USBAUXRLX |
| OEM Jeep Radio  | 2011-2017 Jeep<br>Wrangler                      | N/A                             | N/A                                | N/A                                     | N/A                        | <b>V</b>                                 | ✓* Note 1     | N/A                 | N/A                       | N/A                                    | N/A                                    | N/A                                       |
| X109-WRA<br>X209-WRA  |   | ✓******* Note 7 ✓******* Note 7 | <b>1</b>                           | ✓*** Note 3  ✓*** Note 3                | 1                          | N/A<br>N/A                               | <b>/</b>      | N/A<br>N/A          | N/A<br>N/A                | N/A<br>N/A                             | N/A<br>N/A                             | N/A<br>N/A                                |
| i109-WRA<br>i209-WRA  |   | N/A<br>✓******* Note 7          | N/A                                | N/A<br>✓*** Note 3                      | N/A                        | N/A<br>N/A                               | <i>'</i>      | N/A<br>N/A          | N/A<br>N/A                | N/A<br>N/A                             | N/A<br>N/A                             | N/A<br>N/A                                |
| X110-SLV<br>X110-SRA  | 2014-up 1500-3500<br>Full Size pickups          | ✓******* Note 7 ✓******* Note 7 | <b>√</b>                           | ✓*** Note 3 ✓*** Note 3                 | <b>J</b>                   | N/A<br>N/A                               | N/A<br>N/A    | ✓** Note2 ✓** Note2 | N/A<br>N/A                | N/A<br>N/A                             | N/A<br>N/A                             | N/A<br>N/A                                |
| X009-GM   | 2007-2014 Full<br>Size Truck and<br>SUV         | ✓*******Note 8                  | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | ✓                         | ✓**** Note 4                           | N/A                                    | N/A                                       |
| X009-GM2  | 2007-2013 Full<br>Size Truck                    | ✓********Note 8                 | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | <b>4</b>                  | N/A                                    | N/A                                    | N/A                                       |
| X009-FD1  | 2009-20104 Full<br>Size Truck                   | <b>√</b>                        | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | N/A                       | N/A                                    | N/A                                    | ✓****** Note 6                            |
| X009-FD2  | 2013-2014 Full size<br>Truck(4.2 My Ford)       | ✓                               | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | N/A                       | N/A                                    | N/A                                    | N/A                                       |
| X009-RAM  | 2013-UP Full Size<br>Truck except 8.4<br>screen | ✓                               | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | N/A                       | N/A                                    | <b>√</b> ***** Note 5                  | N/A                                       |
| X009-TND  | 2007-2013 Full<br>Size Truck                    | <b>√</b>                        | N/A                                | N/A                                     | N/A                        | N/A                                      | N/A           | N/A                 | N/A                       | N/A                                    | N/A                                    | N/A                                       |

Note\*1- Must use ALP-HRN-CAMCH and OEM head unit must be flashed by the Jeep dealer to activate reverse signal input

Note\*\*2- KCX-BOSE-GM required on all trucks equiped with factory Bose system

Note \*\*\*3 Relay installation Required

Note \*\*\*\*4 Needed with 2012-2014 Navigation equipped vehicles

Note \*\*\*\*\*5 Needed on Vehicles with Park Assist system to hear chimes

Note \*\*\*\*\*\*6 Due to the limited space in the KTX-009-FD1 radio bezel, the Ford Sync port could not be accommodated in the same location. Follow the instructions below to relocate the USB and AUX ports

Note\*\*\*\*\*\*\*7 The OEM satellite radio tuner is built into the factory head unit. An aftermarket satellite tuner must be used

Note\*\*\*\*\*\*\*\*\*8 On 2007-2013 GM Trucks the OEM satellite radio tuner may be retained if the vehicle is equipped with one.